

Inadequate guardrail at bridge EB and WB